

## Annexure D

## BUILDING SAFETY CERTIFICATE

No. 860

Dated 07/05/2026

It is certified that the existing building **Lipin International School** (name of the building or premises) at **Attitka (Sunari), Teh. -Tauru, Distt.-Nuh ,Pin-122105** (address) is having block (s)/Floor (s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G + 3					

The building is owned/occupied by **Lipin International School, Attitka** (name of the institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD, Nuh** (Name of Department/Govt.) on 04-05-2026 (date of inspection) in the presence of **Sh. Sanjiv Kumar , Secretary, Nuh, Attitka** (name and address of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 04-05-2026 for a period of one years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 04-05-26 at Nuh by

Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: [Signature] Sub Divisional Engineer,  
Provincial Sub Division.

Name: TAPESH KUMAR  
P.W.D B&R Br Nuh

Designation: SDE

Name & Address of Department/ Office: P.W.D B&R Nuh.

**Principal**

Lipin International School  
Attitka (Sunari) Tauru, Distt. Nuh